



# Inspection Report

Inspection Date: 2019/03/13

## Truck

### General Information

<b>Maker</b>	ISUZU
<b>Model Number</b>	ADGFRR90
<b>Year</b>	2005
<b>Mileage (km)</b>	117602
<b>Serial Number</b>	FRR90L3S-7000072

### Note for External Appearance

- ISUZU Smoother transmission
- Year on the seat belt: 2010

### Engine

<b>Model</b>	
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	No
<b>Engine Oil Gauge</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Radiator</b>	OK
<b>Water Pump</b>	No water leak
<b>Injection Pump</b>	No fuel leak

### Note for Control Panel

### Note for Engine

Admin. No. 2019030178

\*This report is only for your reference. We are not responsible for the actual condition of checked item.