



Inspection Report

Inspection Date: 2018/05/29

Roller

General Information

Maker	HITACHI
Model Number	RC45-2
Year	
Hour (h)	1370
Serial Number	60220936

Engine

Model	
Serial Number	
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	OK


Note for External Appearance

The rubber part of the front scraper is lost



Note for Undercarriage

One of the right tires is partly damaged




Note for Operating Component

- The blinkers, the hazard lights, and the head lights are broken
- The sprinkler pump is broken
- The vibration switches and the parking switch are working



Note for Engine

- Oil oozing from the forward-reverse valve
- Oil oozing from around the injection nozzles
- Oil oozing from the front vibration motor
- Oil oozing from around the driving parts (rear)



Admin. No. 2018050709

*This report is only for your reference. We are not responsible for the actual condition of checked item.