Hour (h) 5232

Bucket No

Bucket Size (mm) 550

**General Information** 

rmation		
I	Maker	YANMAR
Model Nu	ımber	Vi040-5B
	Year	2012

No

Meter Working

Small

Serial Number		58644		
Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	riay
Boom	Left	Oil oozing	Scratch	Small
	Right	N/A	N/A	Siliali
Arm		No	Scratch	Small

Undercarriage		
Shoe Type	Rubber	
Swing Circle	Loading	
	Left	Right
Shoe Width (mm)	350	350
Idler	ОК	OK
Sprocket	ОК	OK
Pin Bush	ОК	OK
Upper Roller	ОК	OK
Track Roller	ОК	OK
Shoe Link	ОК	OK

Engine	
Model	
Serial Number	L6242
Engine Oil Leak	No oil leak
Engine Oil Gauge	ОК
Radiator	ОК
Exhaust Color	Normal
Blow-by	Loading
Engine Sound	ОК
Hydraulic Pump	Oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Options	
- CNP	- Speed changer
- Multilever	
- Blade	- Pipings

Inspection Date: 2024/07/31

# Note for External Appearance

- The covers have rust, scratches, and dents
- The canopy has some dents and cracks



#### Note for Upper Structure

- Oil leaks from the swing cylinder The bucket side cutters are missing
- The arm has been reinforced
   Unusual noise near the hydraulic pump
- It does not move straight
- The movements of swing, arm, bucket and left
- turning are not proper

  Oil oozing from the bottom cover

  With quick hitch



# Note for Undercarriage

- The rubber shoes are cracked
- Oil oozing from the reduction drives of the travel motors
- Oil oozing from two of the right lower rollers



## Note for Operating Component

- The seat is torn



## Note for Engine

- Slight blow-by



Admin No.

3000061569