



Inspection Report

Inspection Date: 2018/03/02


Excavators

General Information			
Maker	KUBOTA		
Model Number	U-20-3S		
Year	2008		
Hour (h)	1934	Meter	Working
Serial Number	12920		

Options	
- CNP	- Speed changer
- Multilever	
- Blade	- Pipings


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	No
Bucket Size (mm)		400		

Note for External Appearance
- Repainted - The canopy is damaged - The key hole of the engine cover is broken




Undercarriage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	250	250
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure




Note for Undercarriage
The rubber shoes have deteriorated over time and are partly damaged




Engine	
Model	D1105-K3A
Serial Number	AW6414
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Rust/Oil
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	Oil oozing
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component
The back of the seat is partly torn



Note for Engine
- Oil oozing from the hydraulic control valve and the hydraulic pump - Oil oozing from around the oil cooler hose



Lot No ARA013-0044 Admin No. 2018020537