



Inspection Report

Inspection Date: 2024/07/31

Wheel Loader

General Information

Maker	KUBOTA
Model Number	R430Z
Year	2011
Hour (h)	1663
Serial Number	R430-20622

Upper Structure

Lift Arm Cylinder (Left)	No oil leak
Lift Arm Cylinder (Right)	No oil leak
Bucket Cylinder (Left)	No oil leak
Bucket Cylinder (Right)	No oil leak

Undercarriage

Front Accel	Oil oozing
Rear Accel	Oil oozing

Engine

Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	OK

Documents

Automobile Inspection Certificate	No
--	----

Note for External Appearance

- The cover is rusty and has some scratches



Note for Upper Structure

- The movement of the upper structure is slow. it like lack of hydraulic oil



Note for Operating Component

- Kilometers : 24,333km



Note for Undercarriage

- Oil leak from the hydraulic line around rear accele



Note for Engine



Admin. No. 3000061648

*This report is only for your reference. We are not responsible for the actual condition of checked item.