



# Inspection Report

Inspection Date: 2024/07/12

## Excavators

### General Information

<b>Maker</b>	HITACHI		
<b>Model Number</b>	ZX40UR-5B		
<b>Year</b>	2016		
<b>Hour (h)</b>	2343	<b>Meter</b>	Working
<b>Serial Number</b>	50087		

### Options

- CAB	- Speed changer
- Multilever	
- Blade	
- Arm Crane	

### Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)	540			

### Note for External Appearance



### Undercarriage

<b>Shoe Type</b>	Steel shoes with rubber pads		
<b>Swing Circle</b>	No oil leak		
	<b>Left</b>	<b>Right</b>	
Shoe Width (mm)	300	300	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

### Note for Upper Structure



### Note for Undercarriage



### Engine


<b>Model</b>	3TNV88-EPHB
<b>Serial Number</b>	T5746
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	No oil leak
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	No oil leak
<b>Multi Lever</b>	No oil leak

### Note for Operating Component

- The door of the drivers seat does not keep opening



### Note for Engine



Admin No. 3000061030