



# Inspection Report

Inspection Date: 2022/09/17

## Excavators

### General Information

<b>Maker</b>	SUMITOMO		
<b>Model Number</b>	SH135X-3B		
<b>Year</b>			
<b>Hour (h)</b>	6536	<b>Meter</b>	Working
<b>Serial Number</b>	SMT135X3A00BB7119		

### Options

- |              |                   |
|--------------|-------------------|
| - CAB        | - Speed changer   |
| - Multilever | - Air conditioner |
| - Blade      | - Piping          |

### Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	No	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)	890			

### Note for External Appearance

- The covers are damaged and have some dents
- No fuel cap



### Undercarriage

<b>Shoe Type</b>	Steel	
<b>Swing Circle</b>	Oil oozing	
	<b>Left</b>	<b>Right</b>
<b>Shoe Width (mm)</b>	500	500
<b>Idler</b>	OK	OK
<b>Sprocket</b>	OK	OK
<b>Pin Bush</b>	OK	OK
<b>Upper Roller</b>	OK	OK
<b>Track Roller</b>	OK	NG
<b>Shoe Link</b>	NG	NG

### Note for Upper Structure

- No bucket-side cutters
- Oil oozing from the control valve
- The upper part of the blade has some dents
- The edge of the blade is partly damaged



### Note for Undercarriage

- The shoe links have some kinks
- Some shoes are bent
- The right lower rollers are missing.



### Engine

<b>Model</b>	AJ-4JJ1XYSS-02
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	Yes
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	No oil leak
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	No oil leak
<b>Multi Lever</b>	No oil leak

### Note for Operating Component

- The seat is torn



### Note for Engine



Admin No. 3000042423