



# Inspection Report

Inspection Date: 2019/03/26


## Excavators

General Information			
<b>Maker</b>	KOBELCO		
<b>Model Number</b>	SK75UR-3ES		
<b>Year</b>	2007		
<b>Hour (h)</b>	5091	<b>Meter</b>	Working
<b>Serial Number</b>	YR07-07287		

Options	
- CAB	- Air conditioner
- Multilever	
- Blade	
- Arm Crane	
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)		670		

**Note for External Appearance**  
The connecting part of the arm and boom is slightly bent to the left




Undercarriage			
<b>Shoe Type</b>	Steel shoes with rubber pads		
<b>Swing Circle</b>	No oil leak		
	Left	Right	
<b>Shoe Width (mm)</b>	450	450	
<b>Idler</b>	OK	OK	
<b>Sprocket</b>	OK	OK	
<b>Pin Bush</b>	OK	OK	
<b>Upper Roller</b>	OK	OK	
<b>Track Roller</b>	OK	OK	
<b>Shoe Link</b>	OK	OK	

**Note for Upper Structure**




**Note for Undercarriage**  
Oil oozing from around the swivel



Engine	
<b>Model</b>	CC-4JG1PYA-01
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	Normal
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	No oil leak
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	No oil leak
<b>Multi Lever</b>	No oil leak

**Note for Operating Component**  
The seat is partly torn



**Note for Engine**



Admin No. 2019030436