



Inspection Report

Inspection Date: 2019/07/16

Excavators

General Information

Maker	YANMAR		
Model Number	ViO20-2		
Year	2000		
Hour (h)		Meter	Working
Serial Number	20894B		

Options

- | | |
|--------------|-----------------|
| - CNP | - Speed changer |
| - Multilever | |
| - Blade | - Pipings |

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Big
Bucket		No	No	Big
Bucket Size (mm)		625		

Note for External Appearance

- No serial plate
- A canopy will be attached before shipment according to the seller



Undercarriage

Shoe Type	Rubber	
Swing Circle	Oil oozing	
	Left	Right
Shoe Width (mm)	250	250
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	NG
Shoe Link	OK	OK

Note for Upper Structure

- The boom has been reinforced
- 4 sides of the arm have been reinforced
- The right part of the bucket is deformed
- No boom cylinder covers



Note for Undercarriage

- The surface of the left rubber shoe has been cracked
- Oil oozing from around the right travel motor
- One of the right lower rollers is broken
- No blade cylinder covers



Engine

Model	
Serial Number	
Engine Oil Leak	Oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	Yes
Engine Sound	OK
Hydraulic Pump	Oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Oil oozing
Multi Lever	Oil oozing

Note for Operating Component

- Unable to check the hour meter because its panel has deteriorated over time
- The seat is partly torn



Note for Engine

The engine has been fixed



Admin No. 2019070577