



# Inspection Report

Inspection Date: 2021/03/21

## Truck

### General Information

<b>Maker</b>	MITSUBISHI
<b>Model Number</b>	KC-FE517BD
<b>Year</b>	1999
<b>Mileage (km)</b>	88357
<b>Serial Number</b>	FE517BD-532500

### Note for External Appearance

- The body is worn and has some dents
- The fender is partly deformed

### Engine

<b>Model</b>	4D33
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	No
<b>Engine Oil Gauge</b>	OK
<b>Exhaust Color</b>	White
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Radiator</b>	OK
<b>Water Pump</b>	No water leak
<b>Injection Pump</b>	No fuel leak

### Note for Control Panel

- F5

### Note for Engine

Admin. No. 3000029394

\*This report is only for your reference. We are not responsible for the actual condition of checked item.