



Inspection Report

Inspection Date: 2017/08/09

Excavators

General Information

Maker	YANMAR		
Model Number	Vio50-2		
Year	2002		
Hour (h)	5234	Meter	Working
Serial Number	21671B		

Options

- | | |
|--------------|-----------------|
| - CNP | - Speed changer |
| - Multilever | |
| - Blade | |
| - Arm Crane | |
| - EPA | |

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	Yes	No
Bucket Size (mm)		-		

Note for External Appearance

- Repainted
- The canopy is deformed



Undercarriage

Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	400	400
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

- A standard bucket will be attached before shipment (according to the seller)
- There is a play around the H link



Note for Undercarriage

- The rubber shoes have deteriorated over time
- The right rubber shoes have some cracks



Engine

Model	4TNE88-EBVC
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	Oil oozing
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	Oil oozing

Note for Operating Component



Note for Engine

- Oil oozing from around the hose of the hydraulic pump



Admin No. 2017080171