



# Inspection Report


Inspection Date: 2017/09/13

## Excavators


General Information			
<b>Maker</b>	YANMAR		
<b>Model Number</b>	ViO70-3		
<b>Year</b>	2005		
<b>Hour (h)</b>	4314	<b>Meter</b>	Working
<b>Serial Number</b>	30708B		


Options	
- CAB	- Speed changer
- Multilever	- Air conditioner
- Blade	- Breaker Pippings
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No confirmat
	Right	N/A	N/A	
Arm		No	No	Unchecked
Bucket		No	No	Big
Bucket Size (mm)		-		


Note for External Appearance


Undercarriage		
<b>Shoe Type</b>	Steel shoes with rubber pads	
<b>Swing Circle</b>	No oil leak	
	<b>Left</b>	<b>Right</b>
<b>Shoe Width (mm)</b>	450	450
<b>Idler</b>	OK	OK
<b>Sprocket</b>	OK	OK
<b>Pin Bush</b>	OK	OK
<b>Upper Roller</b>	OK	OK
<b>Track Roller</b>	OK	OK
<b>Shoe Link</b>	OK	OK

Note for Upper Structure
- The upper structure does not have enough power - No bucket


Note for Undercarriage
The rubber pads are partly worn


Engine	
<b>Model</b>	4TNV98-XBV
<b>Serial Number</b>	18120
<b>Engine Oil Leak</b>	Oil oozing
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	No oil leak
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	No confirmation of movement
<b>Multi Lever</b>	No oil leak

Note for Operating Component


Note for Engine


Admin No. 2017090480