



Inspection Report

Inspection Date: 2017/09/16

Excavators

General Information

Maker	YANMAR		
Model Number	ViO30-5		
Year	2006		
Hour (h)	3984	Meter	Working
Serial Number	50743B		

Options

- CNP	- Speed changer
- Multilever	
- Blade	- Breaker Piping
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Big
	Right	N/A	N/A	
Arm		No	No	Big
Bucket		No	No	Big
Bucket Size (mm)		470		

Note for External Appearance

- Repainted
- No caution plate
- No engine cover lock



Undercarriage

Shoe Type	Rubber	
Swing Circle	No confirmation of movement	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	NG	NG

Note for Upper Structure

Rotation is not smooth



Note for Undercarriage

- The rubber shoes have deteriorated over time and are worn
- The rubber shoes are partly cracked
- No left travel motor cover
- The left travel motor has deteriorated over time (oil leak) according to the seller



Engine

Model	3TNV82A-N
Serial Number	-
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	No confirmation of movement
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No confirmation of movement
Multi Lever	No oil leak

Note for Operating Component

- The left safety lever is fixed with a wire
- The seat is partly torn



Note for Engine



Admin No. 2017090405