



Inspection Report


Inspection Date: 2017/10/11

Excavators


General Information			
Maker	YANMAR		
Model Number	Vio20-2		
Year	2003		
Hour (h)	3217	Meter	Not Working
Serial Number	26105B		


Options	
- CNP	- Speed changer
- Multilever	
- Blade	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Unchecked
	Right	N/A	N/A	
Arm		No	No	Unchecked
Bucket		No	No	Unchecked
Bucket Size (mm)				


Note for External Appearance
Repainted



Undercarriage		
Shoe Type	Rubber	
Swing Circle	Unchecked	
	Left	Right
Shoe Width (mm)	250	250
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure
The movement of the upper structure is unchecked


Note for Undercarriage
Traveling motion is unchecked


Engine	
Model	3TNV76-P
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Unchecked
Blow-by	Unchecked
Engine Sound	Unchecked
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component


Note for Engine
The movement of the engine is unchecked


Admin No. 2017100731