



Inspection Report

Inspection Date: 2017/10/10


Excavators

General Information			
Maker	YANMAR		
Model Number	ViO30-5		
Year	2007		
Hour (h)	3388	Meter	Working
Serial Number	51666B		

Options	
- CNP	- Speed changer
- Multilever	
- Blade	
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Big
	Right	N/A	N/A	
Arm		No	No	Big
Bucket		No	No	Unchecked
Bucket Size (mm)		470		


Note for External Appearance



Undercarriage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK


Note for Upper Structure

- The bucket is unable to be attached because the H link and I link are broken
- The bucket cylinder rod is partly bent (according to the seller)



Note for Undercarriage


The rubber shoes have deteriorated over time, are worn, and partly cracked



Engine	
Model	3TNV82A-N
Serial Number	48085
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	N/A
Multi Lever	No oil leak

Note for Operating Component

- The seat is partly torn
- The safety lock lever is broken



Note for Engine



Admin No. 2017100763