



# Inspection Report


Inspection Date: 2018/05/17

## Excavators


General Information			
<b>Maker</b>	KOBELCO		
<b>Model Number</b>	SK75UR-3		
<b>Year</b>	2002		
<b>Hour (h)</b>	7226	<b>Meter</b>	Working
<b>Serial Number</b>	YR04-05026		


Options	
- CAB	
- Multilever	
- Blade	
- Arm Crane	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	Small
	Right	Unchecked	Unchecked	
Arm		No	No	Big
Bucket		No	No	Big
Bucket Size (mm)		780		


Note for External Appearance
Repainted


Undercarriage		
<b>Shoe Type</b>	Steel shoes with rubber pads	
<b>Swing Circle</b>	Oil oozing	
	Left	Right
<b>Shoe Width (mm)</b>	-	-
<b>Idler</b>	OK	OK
<b>Sprocket</b>	OK	OK
<b>Pin Bush</b>	OK	OK
<b>Upper Roller</b>	OK	OK
<b>Track Roller</b>	OK	OK
<b>Shoe Link</b>	OK	OK

Note for Upper Structure


Note for Undercarriage
The swivel has been reinforced to prevent oil leak


Engine	
<b>Model</b>	
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	No oil leak
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	No oil leak
<b>Multi Lever</b>	No oil leak

Note for Operating Component
- An error message appears on the display in the crane mode
- The seat is partly torn
- No air conditioner


Note for Engine


Admin No. 2018050418