



Inspection Report

Inspection Date: 2022/12/08

Excavators

General Information

Maker	HITACHI		
Model Number	ZX30UR-2		
Year	2005		
Hour (h)	4778	Meter	Working
Serial Number	HCM1MF00H00030091		

Options

- CNP
- Multilever
- Blade
- Speed changer

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)		450		

Note for External Appearance

- The right of the front covers have some dents
- The body chassis number (VIN stamp) is unchecked



Undercarriage

Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	300	300	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure

- The tip of the arm has some dents



Note for Undercarriage

- The right & left cover of the travel motors are decayed
- Some rubber pads are lost
- The sprockets are severely worn
- The idlers are slightly worn



Engine

Model	3TNV88-S
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Not enough cooling water
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	Loading...
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component



Note for Engine



Admin No. 3000044528