



Inspection Report

Inspection Date: 2018/08/08

Excavators

General Information

Maker	HITACHI		
Model Number	ZX125US		
Year	2006		
Hour (h)	6456	Meter	Working
Serial Number	HCM1SE00C00011633		

Options

- CAB	- Speed changer
- Multilever	- Air conditioner
- Arm Crane	
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	No	No	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)	850			

Note for External Appearance



Undercarriage

Shoe Type	Steel	
Swing Circle	Oil oozing	
	Left	Right
Shoe Width (mm)	600	600
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	NG
Shoe Link	OK	OK

Note for Upper Structure

- According to the seller, the rotation motor is broken:
 - rotation is slow & UNSTEADY
 - it produces unusual sound
- The body needs to be fixed while transporting
- 1 side of the arm has been reinforced



Note for Undercarriage

2 of the right lower rollers are broken



Engine

Model	BB-4BG1 TRG
Serial Number	4BG1-935915
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Oil leak
Multi Lever	No oil leak

Note for Operating Component

The seat is partly torn



Note for Engine



Admin No. 2018080015