



# Inspection Report

Inspection Date:

## Aerial Work Platform

### General Information

<b>Maker</b>	UPRIGHT
<b>Model Number</b>	MB20
<b>Year</b>	
<b>Hour (h)</b>	
<b>Serial Number</b>	150-06

### Note for External Appearance

### Engine

<b>Model</b>	
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	#N/A
<b>Engine Oil Gauge</b>	#N/A
<b>Exhaust Color</b>	#N/A
<b>Blow-by</b>	#N/A
<b>Engine Sound</b>	#N/A
<b>Radiator</b>	#N/A
<b>Water Pump</b>	#N/A
<b>Injection Pump</b>	#N/A

### Note for Control Panel

### Note for Engine

### Other Information

- After a certain period of time, an error sound will ring and the operation might not work

Admin. No. 3000065770

\*This report is only for your reference. We are not responsible for the actual condition of checked item.