



Inspection Report


Inspection Date: 2018/06/15

Excavators


General Information			
Maker	YANMAR		
Model Number	Vio50-2A		
Year	2003		
Hour (h)	3370	Meter	Working
Serial Number	25626B		


Options	
- CNP	- Speed changer
- Multilever	
- Blade	
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	No
Bucket		Oil oozing	No	Big
Bucket Size (mm)		560		


Note for External Appearance


Undercarriage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	400	400
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure
- The blade gradually drops by itself - Oil leak from the blade cylinder


Note for Undercarriage
- Oil oozing from the reduction drive of the right travel motor - The rubber shoes have deteriorated over time and are partly worn


Engine	
Model	4TNV88-XBV
Serial Number	947
Engine Oil Leak	No oil leak
Engine Oil Gauge	Not enough cooling water
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component


Note for Engine


Admin No. 2018061041