



Inspection Report


Inspection Date: 2018/06/14

Excavators


General Information			
Maker	YANMAR		
Model Number	ViO20-3		
Year	2006		
Hour (h)	3294	Meter	Working
Serial Number	33105b		


Options	
- CNP	
- Multilever	
- Blade	
- EPA	
- Breaker Pipings	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)		415		


Note for External Appearance


Undercarriage			
Shoe Type	Rubber		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	250	250	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure
The boom gradually drops by itself


Note for Undercarriage
The right rubber shoe has deteriorated over time, are worn, and partly cracked


Engine	
Model	3TNV76-P
Serial Number	26356
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component
The seat is partly torn


Note for Engine


Admin No. 2018060945