

Inspection Date: 2017/08/22

General Information		
Maker	HITACHI	
Model Number	ZX135US	
Year	2003	
Hour (h)	7800 Meter	Working
Serial Number	HCM1SC00E00064716	

Options	
- CAB	- Speed changer
	- Air conditioner
- Blade	
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	riay
Boom	Left	No	No	Small
	Right	No	No	Offiaii
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)		880		

Note for External Appeara	nce

Undercarriage		
Shoe Type	Steel shoes with rubber pads	
Swing Circle	Oil oozing	
	Left	Right
Shoe Width (mm)	500	500
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	NG	NG

Note for Upper Structure

- Slide arm
- The arm and blade drop gradually by themselves



Note for Undercarriage

- Both shoes are slightly loose
- The shoe links are worn



Engine	
Model	CC-4BG1T
Serial Number	_
Engine Oil Leak	Oil oozing
Engine Oil Gauge	ОК
Radiator	ОК
Exhaust Color	Normal
Blow-by	No
Engine Sound	ОК
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	-

Note for Operating Component

- The seat is worn
- Broken rear camera



Note for Engine Squeaking timing belt Admin No. 2017080421