



# Inspection Report

Inspection Date: 2018/10/10

## Excavators

### General Information

<b>Maker</b>	KOBELCO		
<b>Model Number</b>	SK007		
<b>Year</b>			
<b>Hour (h)</b>	2072	<b>Meter</b>	Working
<b>Serial Number</b>	PT07279		

### Options


- Blade	
---------	--

### Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)	330			

### Note for External Appearance


The covers are cracked



### Undercarriage


<b>Shoe Type</b>	Rubber	
<b>Swing Circle</b>	Unchecked	
	Left	Right
<b>Shoe Width (mm)</b>	180	180
<b>Idler</b>	OK	OK
<b>Sprocket</b>	OK	OK
<b>Pin Bush</b>	OK	OK
<b>Upper Roller</b>	OK	OK
<b>Track Roller</b>	OK	OK
<b>Shoe Link</b>	OK	OK

### Note for Upper Structure



### Note for Undercarriage

Oil oozing from the bottom of the body




### Engine

<b>Model</b>	2TN66L-UYB
<b>Serial Number</b>	8960
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	Not enough cooling water
<b>Radiator</b>	Normal
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	No oil leak
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	No oil leak
<b>Multi Lever</b>	-

### Note for Operating Component

- The seat is partly torn
- The accel lever is broken (RPM won't go up)



### Note for Engine



Admin No. 2018100025