



Inspection Report

Inspection Date: 2022/06/17

Excavators

General Information

Maker	HITACHI		
Model Number	ZX30U-3		
Year	2010		
Hour (h)	5055	Meter	Working
Serial Number	HCM1NE00A00020777		

Options

- CNP	- Speed changer
- Multilever	
- Blade	
- Arm Crane	
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	No	No	
Arm		No	No	No
Bucket		Oil oozing	No	No
Bucket Size (mm)				

Note for External Appearance

- The left side of the body is dented and cracked
- The right side of the body is dented
- The VIN is unchecked



Undercarriage

Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

- No bucket



Note for Undercarriage



Engine

Model	3TNV88-BPHB
Serial Number	C8396
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Not enough cooling water
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	Oil oozing

Note for Operating Component

- The seat is torn



Note for Engine

- The battery is flat. Operational condition has been checked with the booster cables. The machine is in normal working condition.
- The engine speed changer does not work
- The cell motor does not work well (the diving motion is bad)



Admin No. 3000040315