



Inspection Report

Inspection Date: 2018/08/22


Excavators

General Information			
Maker	HITACHI		
Model Number	EX40-2		
Year	1995		
Hour (h)	1249	Meter	Working
Serial Number	1B8-03665		

Options	
- CNP	- Speed changer
- Blade	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		550		


Note for External Appearance



Undercarriage			
Shoe Type	Rubber		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	400	400	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	


Note for Upper Structure

The blade is partly deformed



Note for Undercarriage


The rubber shoes have deteriorated over time and are worn



Engine	
Model	V2203KA
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak


Note for Operating Component

The safety lever is stiff



Note for Engine

The timing belt is severely worn



Lot No ARA017-0031 Admin No. 2018080463