



Inspection Report


Inspection Date: 2018/06/12

Excavators


General Information			
Maker	YANMAR		
Model Number	Vio30-5		
Year	2006		
Hour (h)	4584	Meter	Working
Serial Number	50630B		


Options	
- CNP	- Speed changer
- Multilever	
- Blade	
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		Oil oozing	No	Small
Bucket		Oil oozing	No	Big
Bucket Size (mm)		480		


Note for External Appearance
Repainted


Undercarriage			
Shoe Type	Rubber		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	300	300	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure
- The tip of the arm has some dents
- One of the bucket-pin collars is lost


Note for Undercarriage
The left rubber shoe is damaged (please check the pictures)


Engine	
Model	3TNV82A-N
Serial Number	35779
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component
The seat has been fixed


Note for Engine


Admin No. 2018060976