Inspection Date: 2018/10/15

| General Information | | | |
|---------------------|----------|-------|---------|
| Maker | YANMAR | | |
| Model Number | ViO30-5B | | |
| Year | 2011 | | |
| Hour (h) | 3006 | Meter | Working |

Serial Number 54652B

| Options | |
|--------------|-----------|
| - CNP | |
| - Multilever | |
| - Blade | - Pipings |
| | |
| | |

| Upper Structure | | | | | |
|------------------------|---------|------------|--------------|-------|--|
| | | Су | Cylinder | | |
| | | Oil Leak | Scratch/Rust | Play | |
| Boom | Left | Oil oozing | No | Small | |
| | Right | N/A | N/A | Oman | |
| | Arm | No | No | Small | |
| Bucket No No Small | | Small | | | |
| Bucket Siz | ze (mm) | 470 | | | |

| Note for External Appearance | |
|------------------------------|--|
| | |
| | |
| | |
| | |
| | |

Note for Upper Structure

| Undercarriage | | |
|-----------------|------------------------------|-------|
| Shoe Type | Steel shoes with rubber pads | |
| Swing Circle | No oil leak | |
| | Left | Right |
| Shoe Width (mm) | 300 | 300 |
| Idler | OK | OK |
| Sprocket | OK | OK |
| Pin Bush | OK | OK |
| Upper Roller | OK | OK |
| Track Roller | OK | OK |
| Shoe Link | OK | OK |

| Note for Undercarriage | |
|--|--|
| - Oil leak from the lower rollers - The rubber pads have deteriorated over time and are worn | |





