



Inspection Report

Inspection Date: 2017/07/13

Excavators

General Information

Maker	YANMAR		
Model Number	Vio10-2		
Year	2007		
Hour (h)	1149	Meter	Working
Serial Number	23702B		

Options

-	- Speed changer
-	-
- Blade	-
-	-
- EPA	-

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	Big
Bucket Width (mm)		370		

Note for External Appearance

Repainted



Note for Upper Structure



Undercarriage

Shoe Type	Rubber		
Swing Circle	No oil leak		
		Left	Right
Shoe Width (mm)	180	180	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Undercarriage

- Width adjustable
- Oil leak from around the travel motor because the hydraulic hose is damaged



Engine

Model	3TNV70-WBVB
Serial Number	24369
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	N/A
Multi Lever	-

Note for Operating Component



Note for Engine



Admin No. 2017070144