



# Inspection Report

Inspection Date: 2019/06/18

## Excavators

### General Information

<b>Maker</b>	KOBELCO		
<b>Model Number</b>	SK015		
<b>Year</b>			
<b>Hour (h)</b>	1717	<b>Meter</b>	Working
<b>Serial Number</b>	PU-03399		

### Options

- CNP
- Blade

### Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	No
Bucket Size (mm)	355			

### Note for External Appearance



### Undercarriage

<b>Shoe Type</b>	Rubber	
<b>Swing Circle</b>	No oil leak	
	<b>Left</b>	<b>Right</b>
<b>Shoe Width (mm)</b>	230	230
<b>Idler</b>	OK	OK
<b>Sprocket</b>	OK	OK
<b>Pin Bush</b>	OK	OK
<b>Upper Roller</b>	OK	OK
<b>Track Roller</b>	OK	OK
<b>Shoe Link</b>	OK	NG

### Note for Upper Structure



### Note for Undercarriage

- The right rubber shoe is partly cracked
- One of the links of the right rubber shoe was lost
- Width adjustable



### Engine

<b>Model</b>	3TNA72L-UTBB
<b>Serial Number</b>	97606
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	Normal
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	No oil leak
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	No oil leak
<b>Multi Lever</b>	-

### Note for Operating Component



### Note for Engine



Admin No. 2019060456