



Inspection Report

Inspection Date: 2019/07/16

Excavators

General Information

Maker	YANMAR		
Model Number	ViO30-1		
Year	1997		
Hour (h)	5164	Meter	Working
Serial Number	11478B		

Options

- | | |
|--------------|-----------------|
| - CNP | - Speed changer |
| - Multilever | |
| - Blade | |

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	Small
	Right	N/A	N/A	
Arm		No	No	Big
Bucket		No	Yes	Big
Bucket Size (mm)		525		

Note for External Appearance

- The serial plate is partly damaged
- The cracks of the right side cover have been fixed
- The upper and lower parts of the blade are deformed



Undercarriage

Shoe Type	Rubber	
Swing Circle	Oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

- The boom gradually drops by itself
- 3 sides of the boom have been reinforced
- The boom has been fixed
- The bucket and the blade are worn and rusty



Note for Undercarriage

The rubber shoes in the picture will be replaced with different ones with normal condition according to the seller



Engine

Model	3TNE82A-BVA
Serial Number	
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	Oil oozing
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	Oil oozing

Note for Operating Component

The speed pedal is stiff



Note for Engine



Admin No. 2019070583