

Inspection Date: 2021/08/13

General Information		
Maker	HITACHI	
Model Number	ZX20U	
Year	2014	
Hour (h)	1766 Meter	Replaced
Serial Number	HCM1MY00T00010973	

Options	
- CNP	- Speed changer
- Multilever	
- Blade	- Pipings
- EPA	

Upper Structure					
		Cylinder		Play	
		Oil Leak	Scratch/Rust	1 lay	
Boom	Left	No	No	No	
	Right	N/A	N/A	140	
Arm		No	No	No	
Bucket		No	No	No	
Bucket Size (mm) 400					
Bucket Oil	-0 (,	400			

		Cylinder		Play	
		Oil Leak	Scratch/Rust	1 lay	
Boom	Left	No	No	No	
Boom	Right	N/A	N/A	140	
	Arm		No	No	
Bucket		No	No	No	
Bucket Siz	Bucket Size (mm)		400		

Undercarriage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	250	250
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	ОК
Track Roller	OK	ОК
Shoe Link	OK	OK

Shoe Link	ОК	ОК	
Engine			
Model	S773L		
Serial Number			
Engine Oil Leak	No oil leak		
Engine Oil Gauge	ОК		
Radiator	OK		
Exhaust Color	Normal		
Blow-by	No		
Engine Sound	ок		
Hydraulic Pump	No oil leak		
Water Pump	No water leak		

Oil Cooler No oil leak Motor No oil leak Multi Lever No oil leak

Note for External Appearance - The right side of the body has some - The rear right part of the body is cracked

Note for Upper Structure	
- 4 sides of the arm have been reinforced	





