



Inspection Report


Inspection Date: 2019/02/22

Excavators


General Information			
Maker	KUBOTA		
Model Number	RX-201		
Year	1993		
Hour (h)	2598	Meter	Not Working
Serial Number	10355		


Options	
- CNP	
- Blade	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	Scratch	Unchecked
	Right	N/A	N/A	
Arm		No	No	Unchecked
Bucket		Oil leak	Yes	Unchecked
Bucket Size (mm)		400		


Note for External Appearance



Undercarriage			
Shoe Type	Rubber		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	250	250	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure
Operational condition of the upper structure is unchecked


Note for Undercarriage
- Traveling motion is unchecked
- The rubber shoes have deteriorated over time and are partly worn
- The shoes are loose


Engine	
Model	
Serial Number	
Engine Oil Leak	Oil oozing
Engine Oil Gauge	Unchecked
Radiator	Unchecked
Exhaust Color	Unchecked
Blow-by	Unchecked
Engine Sound	Unchecked
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	-

Note for Operating Component
The seat is partly torn


Note for Engine
Operational condition of the engine is unchecked


Admin No. 2019020505