



Inspection Report


Inspection Date: 2017/09/08

Excavators


General Information			
Maker	KUBOTA		
Model Number	RX-303		
Year	2001		
Hour (h)	4725	Meter	Working
Serial Number	30152		


Options	
- CNP	- Speed changer
- Multilever	
- Blade	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	Big
	Right	N/A	N/A	
Arm		No	No	Big
Bucket		No	No	Big
Bucket Size (mm)		430		


Note for External Appearance
Repainted


Undercarriage		
Shoe Type	Steel shoes with rubber pads	
Swing Circle	No confirmation of movement	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	NG
Shoe Link	OK	OK

Note for Upper Structure
- Not smooth rotation
- The offset boom has been welded


Note for Undercarriage
- Two of the left rubber pads are lost
- Three of the right rubber pads are lost
- Oil oozing from two of the right lower rollers


Engine	
Model	D1503
Serial Number	01W0286
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component
An error sign of the arm sensor appears on the display


Note for Engine


Lot No ARA009-0049 Admin No. 2017090009