



# Inspection Report


Inspection Date: 2018/11/21

## Excavators


General Information			
<b>Maker</b>	KOBELCO		
<b>Model Number</b>	SK60SR		
<b>Year</b>	2001		
<b>Hour (h)</b>	5338	<b>Meter</b>	Working
<b>Serial Number</b>	YT01-03461		

Options	
- CAB	
- Multilever	
- Blade	- Breaker Pipings


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	No
	Right	N/A	N/A	
Arm		Oil oozing	No	No
Bucket		No	No	Small
Bucket Size (mm)		700		


Note for External Appearance


Undercarriage			
<b>Shoe Type</b>	Steel shoes with rubber pads		
<b>Swing Circle</b>	Oil oozing		
	Left	Right	
<b>Shoe Width (mm)</b>	450	450	
<b>Idler</b>	OK	OK	
<b>Sprocket</b>	OK	OK	
<b>Pin Bush</b>	OK	OK	
<b>Upper Roller</b>	OK	OK	
<b>Track Roller</b>	OK	OK	
<b>Shoe Link</b>	OK	OK	

Note for Upper Structure
- Unable to lift up the body with the boom - The edges of the blade are partly deformed


Engine	
<b>Model</b>	4JB1
<b>Serial Number</b>	204955
<b>Engine Oil Leak</b>	Oil oozing
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	Normal
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	Oil oozing
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	Unchecked
<b>Multi Lever</b>	No oil leak

Note for Undercarriage
The rubber pads have deteriorated over time, are worn, and some of them are lost


Note for Operating Component


Note for Engine


Admin No. 2018110196