Inspection	Date:	2019/07/16

General Information	
Maker	YANMAR
Model Number	ViO20-2
Year	2002
Hour (h)	6276 <b>Meter</b> Working
Serial Number	21804B

Options	
- CNP	- Speed changer
- Multilever	
- Blade	- Pipings
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	1 lay
Boom	Left	Oil oozing	No	Small
Boom	Right	N/A	N/A	Oman
	Arm	No	No	Small
Bucket		No	No	Unchecked
Bucket Size (mm) 580				

Note for External Appearance	
Repainted	

Undercarriage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	240	240
idler	ОК	OK
Sprocket	ОК	OK
Pin Bush	ОК	OK
Upper Roller	ОК	OK
Track Roller	ОК	OK
Shoe Link	ОК	OK

## Note for Upper Structure

- A standard bucket will be attached before shipment
- The right part of the bucket is deformed
- 1 side of the arm has been reinforced



Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	240	240	
ldler	OK	OK	
Sprocket	ОК	OK	
Pin Bush	ОК	ОК	
Upper Roller	OK	OK	
Track Roller	ОК	OK	
Shoe Link	ОК	ОК	
Engine			

Note for Undercarriage	

Engine	
Model	3TNE74-ENBV
Serial Number	N10727
Engine Oil Leak	No oil leak
Engine Oil Gauge	Rust/Oil
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	ОК
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

## Note for Operating Component

- The upper part of the canopy is
- The lower part of the left control lever is damaged



Note for Engine		
	Admin No.	2019070578