

Inspection Report

Inspection Date: 2023/09/07

Excavators

General Information				
Maker	YANMAR			
Model Number	ViO35-6			
Year	2017			
Hour (h)	4604 Meter	Working		
Serial Number	6F135			

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	i lay
Boom	Left	No	No	No
	Right	N/A	N/A	INO
	Arm	No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		600		
Bucket Size (mm)		600		
	Arm Bucket	No No	No	Small

Undercarriage

endereannage		
Shoe Type	Rubber	
Swing Circle	Oil oozing	
	Left	Right
Shoe Width (mm)	300	300
Idler	ОК	ОК
Sprocket	ОК	ОК
Pin Bush	ОК	ОК
Upper Roller	ОК	ОК
Track Roller	ОК	ОК
Shoe Link	ОК	ОК

EngineModel3TNV88-ESBVSerial NumberV4772Engine Oil LeakNo oil leakEngine Oil GaugeOKRadiatorOKRadiatorNormalBlow-byNoBlow-byNo oil leakHydraulic PumpNo oil leakOil CoolerNo vater leakOil CoolerNo oil leakMotor IleakNo oil leakMotor IleakNo oil leakMotor IleakNo oil leak

Options - CAB - Speed changer - Multilever - Blade - Pipings - Arm Crane

Note for External Appearance

- The covers have some scratches



Note for Upper Structure

- No bucket side cutters

Note for Undercarriage - The rubber shoe surfaces are worn

Note for Operating Component

With quick hitch (one-touch)With air blower



Note for Engine		
	Admin No.	3000050940

*This report is only for your reference. We are not responsible for the actual condition of checked item.