



# Inspection Report

Inspection Date: 2018/06/12

## Roller

### General Information

<b>Maker</b>	SAKAI
<b>Model Number</b>	TW350-1
<b>Year</b>	2001
<b>Hour (h)</b>	1759
<b>Serial Number</b>	10650

### Engine

<b>Model</b>	3LD1 PA-29
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Water Pump</b>	No water leak
<b>Radiator</b>	Rust/Oil


### Note for External Appearance

Repainted



### Note for Undercarriage

The hub unit of the left rear tire is deformed according to the seller



### Note for Operating Component

The seat is partly torn



### Note for Engine

The radiator does not have enough water



Admin. No. 2018061185

\*This report is only for your reference. We are not responsible for the actual condition of checked item.