

Inspection Date: 2017/08/08

General Information		
Maker	YANMAR	
Model Number	ViO50-5	
Year	2005	
Hour (h)	3670 Meter	Working
Serial Number	50532B	

Options	
- CNP	- Speed changer
- Multilever	
- Blade	
- EPA	

Upper Structure					
		Cylinder		Play	
		Oil Leak	Scratch/Rust	riay	
Boom	Left	No	No	Small	
Boom	Right	N/A	N/A	Offiaii	
	Arm	No	No	Small	
	Bucket	No	No	Small	
Bucket Size (mm) 610					

Note for External Appearance	
Repainted	

Undercarriage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	400	400
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure	

	Left	Right
Shoe Width (mm)	400	400
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK
Engine		

Note for Undercarriage	
- The speed changer is not in a good condition	
- The rubber shoes are loose	



Engine	
Model	4TNV88-P
Serial Number	19487
Engine Oil Leak	No oil leak
Engine Oil Gauge	ОК
Radiator	ОК
Exhaust Color	Normal
Blow-by	No
Engine Sound	ОК
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak



