



# Inspection Report

Inspection Date: 2024/08/14

## Excavators

### General Information

<b>Maker</b>	YANMAR		
<b>Model Number</b>	ViO30-5B		
<b>Year</b>	2012		
<b>Hour (h)</b>	3140	<b>Meter</b>	Working
<b>Serial Number</b>	56092		

### Options

- CAB	- Speed changer
- Multilever	
- Blade	
- Arm Crane	
- EPA	

### Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		Oil oozing	No	Big
Bucket		No	No	Big
Bucket Size (mm)	495			

### Note for External Appearance




### Undercarriage

<b>Shoe Type</b>	Steel shoes with rubber pads		
<b>Swing Circle</b>	No oil leak		
	<b>Left</b>	<b>Right</b>	
Shoe Width (mm)	300	300	
Idler	NG	NG	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	NG	NG	

### Note for Upper Structure




### Note for Undercarriage

- Some rubber pads are worn or missing
  - The idlers are slightly worn
- 

### Engine

<b>Model</b>	3TNV82A-NBV2		
<b>Serial Number</b>	98612		
<b>Engine Oil Leak</b>	No oil leak		
<b>Engine Oil Gauge</b>	OK		
<b>Radiator</b>	OK		
<b>Exhaust Color</b>	Normal		
<b>Blow-by</b>	No		
<b>Engine Sound</b>	OK		
<b>Hydraulic Pump</b>	No oil leak		
<b>Water Pump</b>	No water leak		
<b>Oil Cooler</b>	No oil leak		
<b>Motor</b>	No oil leak		
<b>Multi Lever</b>	No oil leak		

### Note for Operating Component

- The arm crane monitor is broken; numbers are not displayed
  - With air blower and heater
- 

### Note for Engine



Admin No. 3000062504