Inspection Date: 2020/02/04

General Information		
Maker	HITACHI	
Model Number	ZX30U-2	
Year	2006	
Hour (h)	3630 Meter	Working
Sorial Number	HCM1M700L00012023	

Options	
- CNP	
- Multilever	
- Blade	- Pipings
- EPA	

Upper Structure					
		Cylinder		Play	
		Oil Leak	Scratch/Rust		
Boom	Left	No	No	Small	
Boom	Right	N/A	N/A	Siliali	
	Arm	No	No	Small	
	Bucket	No	No	Small	
Bucket Size (mm) 440					

Note for External Appearance	
The body is rusty and has some scratches	


Note for Upper Structure

Note for Operating Component

Undercarriage		
Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	ОК
Sprocket	OK	ОК
Pin Bush	OK	ОК
Upper Roller	OK	OK
Track Roller	OK	ОК
Shoe Link	ОК	OK

Note for Undercarriage	
- The rubbers have peeled off - One of the shoe plates is deformed	

Engine	
Model	3TNV88-N
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	ОК
Radiator	ОК
Exhaust Color	Normal
Blow-by	No
Engine Sound	ОК
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak



Admin No. 3000000676