



Inspection Report

Inspection Date: 2019/11/05


Excavators

| General Information | | | |
|----------------------|----------------------|--------------|---------|
| Maker | HITACHI | | |
| Model Number | ZX75US-A | | |
| Year | | | |
| Hour (h) | 5379 | Meter | Working |
| Serial Number | HCM1CG00G00C00040048 | | |

| Options | |
|--------------|-------------------|
| - CAB | - Speed changer |
| - Multilever | - Air conditioner |
| - Blade | - PIPINGS |


| Upper Structure | | | | |
|------------------|-------|----------|--------------|-------|
| | | Cylinder | | Play |
| | | Oil Leak | Scratch/Rust | |
| Boom | Left | No | Scratch | No |
| | Right | No | No | |
| Arm | | No | No | No |
| Bucket | | No | No | Small |
| Bucket Size (mm) | | 650 | | |

Note for External Appearance




| Undercarriage | | | |
|------------------------|------------------------------|--------------|--|
| Shoe Type | Steel shoes with rubber pads | | |
| Swing Circle | No oil leak | | |
| | Left | Right | |
| Shoe Width (mm) | 450 | 450 | |
| Idler | OK | OK | |
| Sprocket | OK | OK | |
| Pin Bush | OK | OK | |
| Upper Roller | OK | OK | |
| Track Roller | OK | OK | |
| Shoe Link | OK | OK | |

Note for Upper Structure
The bottom of the bucket is worn




Note for Undercarriage
The rubber pads are severely worn




| Engine | |
|-------------------------|---------------|
| Model | 4JG1 |
| Serial Number | 213963 |
| Engine Oil Leak | Oil oozing |
| Engine Oil Gauge | OK |
| Radiator | OK |
| Exhaust Color | Normal |
| Blow-by | No |
| Engine Sound | OK |
| Hydraulic Pump | No oil leak |
| Water Pump | No water leak |
| Oil Cooler | No oil leak |
| Motor | No oil leak |
| Multi Lever | No oil leak |

Note for Operating Component



Note for Engine
Hydraulic oil is not enough



Admin No. 2019101272