



# Inspection Report

Inspection Date: 2019/07/16

## Excavators

### General Information

<b>Maker</b>	YANMAR		
<b>Model Number</b>	ViO35-3		
<b>Year</b>	2004		
<b>Hour (h)</b>	6823	<b>Meter</b>	Working
<b>Serial Number</b>	30746B		

### Options

- CNP	- Speed changer
- Multilever	
- Blade	- PIPINGS
- EPA	

### Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)	520			

### Note for External Appearance

Quick hitch



### Undercarriage

<b>Shoe Type</b>	Rubber	
<b>Swing Circle</b>	No oil leak	
	<b>Left</b>	<b>Right</b>
<b>Shoe Width (mm)</b>	300	300
<b>Idler</b>	OK	OK
<b>Sprocket</b>	OK	OK
<b>Pin Bush</b>	OK	OK
<b>Upper Roller</b>	OK	OK
<b>Track Roller</b>	OK	OK
<b>Shoe Link</b>	OK	OK

### Note for Upper Structure

- No boom cylinder covers
- 4 sides of the arm have been reinforced



### Note for Undercarriage

No oil leak from the travel motors according to the seller



### Engine

<b>Model</b>	3TNV82A-XBV
<b>Serial Number</b>	11085
<b>Engine Oil Leak</b>	Oil oozing
<b>Engine Oil Gauge</b>	Rust/Oil
<b>Radiator</b>	Normal
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	Oil oozing
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	Oil oozing
<b>Multi Lever</b>	Oil oozing

### Note for Operating Component



### Note for Engine

The engine hood does not have its key cylinder



Admin No. 2019070580