



# Inspection Report


Inspection Date: 2018/07/18

## Excavators


General Information			
<b>Maker</b>	SUMITOMO		
<b>Model Number</b>	SH125X-3B		
<b>Year</b>	2008		
<b>Hour (h)</b>	4167	<b>Meter</b>	Working
<b>Serial Number</b>	SC7148		


Options	
- CAB	- Speed changer
- Multilever	- Air conditioner
- Arm Crane	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Unchecked
	Right	No	No	
Arm		No	No	Unchecked
Bucket		No	No	Unchecked
Bucket Size (mm)				


Note for External Appearance


Undercarriage			
<b>Shoe Type</b>	Steel shoes with rubber pads		
<b>Swing Circle</b>	Oil oozing		
	<b>Left</b>	<b>Right</b>	
<b>Shoe Width (mm)</b>	500	500	
<b>Idler</b>	OK	OK	
<b>Sprocket</b>	OK	OK	
<b>Pin Bush</b>	OK	OK	
<b>Upper Roller</b>	OK	OK	
<b>Track Roller</b>	OK	OK	
<b>Shoe Link</b>	OK	OK	

Note for Upper Structure


Note for Undercarriage
- The rubber pads have deteriorated over time and are partly worn - Complete washing is not applicable


Engine	
<b>Model</b>	AJ-4JJ1XYSS-02
<b>Serial Number</b>	107681
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	Normal
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	No oil leak
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	Oil oozing
<b>Multi Lever</b>	Oil oozing

Note for Operating Component
An error message appears on the display in the crane mode


Note for Engine


Admin No. 2018070744