



# Inspection Report

Inspection Date: 2022/08/31

## Excavators

### General Information

<b>Maker</b>	HITACHI		
<b>Model Number</b>	ZX75US-3		
<b>Year</b>	2014		
<b>Hour (h)</b>	3102	<b>Meter</b>	Working
<b>Serial Number</b>	HCM1P300E00066189		

### Options

- CAB	- Speed changer
- Multilever	- Air conditioner
- Blade	- Piping
- EPA	

### Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)	655			

### Note for External Appearance



### Note for Upper Structure

- The bucket side cutters are missing
- The arm has been reinforced



### Undercarriage

<b>Shoe Type</b>	Rubber	
<b>Swing Circle</b>	No oil leak	
	<b>Left</b>	<b>Right</b>
<b>Shoe Width (mm)</b>	450	450
<b>Idler</b>	OK	OK
<b>Sprocket</b>	OK	OK
<b>Pin Bush</b>	OK	OK
<b>Upper Roller</b>	OK	OK
<b>Track Roller</b>	OK	OK
<b>Shoe Link</b>	OK	OK

### Note for Undercarriage



### Engine

<b>Model</b>	AU-4LE2XYS-01
<b>Serial Number</b>	4LE2-621927
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	No oil leak
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	No oil leak
<b>Multi Lever</b>	No oil leak

### Note for Operating Component



### Note for Engine



Admin No. 3000042432