



# Inspection Report

Inspection Date: 2018/06/14

## Excavators

General Information			
Maker	YANMAR		
Model Number	VIO20-3		
Year	2006		
Hour (h)	2811	Meter	Not Working
Serial Number	33089B		

Options	
- CNP	- Speed changer
- Multilever	
- Blade	


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Unchecked
	Right	N/A	N/A	
Arm		No	No	Unchecked
Bucket		No	No	Unchecked
Bucket Size (mm)		400		

Note for External Appearance
- The right side cover has some dents
- The body is partly painted




Undercarriage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	250	250
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure
Upper structure movement is unchecked




Note for Undercarriage
- Traveling motion is unchecked
- The rubber shoes have deteriorated over time and are worn
- Oil oozing from the left idler




Engine	
Model	3TNV76-P
Serial Number	26252
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Unchecked
Exhaust Color	Unchecked
Blow-by	Unchecked
Engine Sound	Unchecked
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component



Note for Engine
- Engine movement is unchecked
- The starter is broken according to the seller



Admin No. 2018060908