



Inspection Report

Inspection Date: 2024/07/30

Excavators

General Information

Maker	KOBELCO		
Model Number	SK30UR-2		
Year	1999		
Hour (h)	894	Meter	Replaced
Serial Number	PR03635		


Options

- CNP	- Speed changer
- Multilever	
- Blade	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)	400			


Note for External Appearance

- Repainted
 - The engine room cover is cracked
 - The body is deteriorated, has scratches and rust
- 

Undercarriage

Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

- The bucket side cutters are missing
 - The boom cylinder is rusted
 - The bucket cylinder is rusted
- 


Note for Undercarriage




Engine

Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	Oil shortage
Radiator	Not enough cooling water
Exhaust Color	Unchecked
Blow-by	Unchecked
Engine Sound	Unchecked
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	-

Note for Operating Component

- Houu meter is unknown
 - The seat is damaged and rusted
- 

Note for Engine

- The starter motor is broken
 - Operating condition is unchecked because the engine does not start
- 

Admin No. 3000061125