



Inspection Report

Inspection Date: 2026/07/19

Excavators

General Information

#ERROR!	KUBOTA		
Model Number	U40-6		
Year	2015		
Hour (h)	5081	Meter	Working
Serial Number	13876		

Options

- | | |
|--------------|-------------------|
| - CNP | - Speed changer |
| - Multilever | |
| - Blade | - Breaker Pipings |

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		Oil leak	No	Unchecked
Bucket Size (mm)		540		

Note for External Appearance

- With a standard bucket



Undercarriage

Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	400	400
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

- With a standard bucket
- The bucket cylinder is bent (Due to a severe oil leak, temporary leak repair has been carried out)



Note for Undercarriage

- The rubber pads on both sides are worn



Engine

Model	V2607-DI-EU7
Serial Number	V2607-8FC0565
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component



Note for Engine



Admin No. 3000087712

*This report is only for your reference. We are not responsible for the actual condition of checked item.