



# Inspection Report

Inspection Date: 2017/09/13

## Roller

### General Information

<b>Maker</b>	SAKAI
<b>Model Number</b>	TW500W
<b>Year</b>	1999
<b>Hour (h)</b>	4134
<b>Serial Number</b>	VTW15-50527

### Engine

<b>Model</b>	4LB1 PA-06
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Water Pump</b>	No water leak
<b>Radiator</b>	OK

### Note for External Appearance

- Repainted
- Both grips of the engine room door are damaged



### Note for Undercarriage

10.5/80-16



### Note for Operating Component



### Note for Engine



Admin. No. 2017090053

\*This report is only for your reference. We are not responsible for the actual condition of checked item.