



Inspection Report


Inspection Date: 2018/06/15

Excavators


General Information			
Maker	YANMAR		
Model Number	Vio30-5		
Year	2006		
Hour (h)	4717	Meter	Working
Serial Number	50698B		


Options	
- CNP	- Speed changer
- Multilever	
- Blade	- Piping
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)		470		


Note for External Appearance



Undercarriage			
Shoe Type	Rubber		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	300	300	
Idler	NG	OK	
Sprocket	OK	NG	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure
- The back of the arm has some dents - The bottom of the bucket is worn


Note for Undercarriage
The left rubber shoe is loose


Engine	
Model	3T N V82A—N
Serial Number	36143
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component


Note for Engine
The fuel filter is detached


Admin No. 2018060995