



Inspection Report


Inspection Date: 2018/06/13

Excavators


General Information			
Maker	YANMAR		
Model Number	ViO30-3		
Year	2004		
Hour (h)	2824	Meter	Working
Serial Number	30990B		


Options	
- CNP	- Speed changer
- Multilever	
- Blade	- Pippings
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Big
	Right	N/A	N/A	
Arm		Oil leak	No	Big
Bucket		No	No	Big
Bucket Size (mm)		470		


Note for External Appearance
Repainted



Undercarriage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure
- Oil leak from the blade cylinder
- The bucket has a hole


Note for Undercarriage
The rubber shoes have deteriorated over time, are worn, and partly cracked


Engine	
Model	3TNV 82A-XBV
Serial Number	13267
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	-

Note for Operating Component
Unable to check the multi lever because its cover is stuck and won't open


Note for Engine
Oil leak from around the hydraulic pump


Admin No. 2018060986